State	Proj. No.	Sheet No.
MD		



DECK REPAIR WITH
VOID TUBE REPLACEMENT



SUPERSTRUCTURE REPAIR (UNFORMED)

① 2¼" (min.) Low Slump Concrete Wearing Surface ② Existing 2" Low Slump Concrete Wearing Surface



REPAIRING CONCRETE DECK (HALF-SOLING)

Detailed
Checked

Note: This drawing is not to scale. Follow dimensions.

Sheet No. of

COUNTY VSR01